

City of Taunton - Cost Estimation for Polling Locations

| |
|--|
| City Priorities |
| Priority 1: Program Access |
| Priority 2: Safety |
| Priority 3: Approach and Entrance |
| Priority 4: Access to Goods and Services |
| Priority 5: Toilet or Bathing Rooms |
| Priority 6: Additional Access |

| |
|--|
| *Cost Estimate Notes: |
| - Cost of design is not included |
| - Does not include costs when note indicates future work |
| - Labor cannot be estimated for all remedies |
| - There is no cost noted when it's presumed to be a maintenance issue. |
| Estimates are intended as a guide to budgeting access modifications and are not intended to be absolutely comprehensive or definitive. |

| |
|---|
| ** 'Dependent on Distance' |
| Each linear foot of 3 foot wide asphalt costs \$13. Each case requires the City to determine the actual distance to be covered. |
| The total calculation does not include these costs. |

| Information Provided by Institute for Human Centered Design | | | | | | | | | | Information Provided by City of Taunton | | | | |
|---|---------------------------|-----------------|---|--|--------------------------|---------------|------------------------------|---|-----------------------------------|---|-------------------------|---------------------------------|-----------------|----------------------|
| FACILITY | REFERENCE # | FB WORK ORDER # | ELEMENT | ISSUE / PHYSICAL BARRIER | LOCATION WITHIN FACILITY | CITY PRIORITY | PRIORITY FOR BARRIER REMOVAL | ACTION FOR BARRIER REMOVAL | ESTIMATED COST OF BARRIER REMOVAL | PROJECT START DATE | PROJECT COMPLETION DATE | RESPONSIBLE FOR BARRIER REMOVAL | BARRIER REMOVED | X |
| Liberty Christian Center | 6-134,6-132,6-133 | | Entrance Door | Doorway at-grade but transition > 1/2" | 1A | Priority 3 | Approach & Entrance | Repair threshold at door, secure walk-off mat. | \$500.00 | 2016 | | City Clerk | | |
| Liberty Christian Center | 6-130 | | Parking | If designated accessible ____ no access aisle (if not parallel space) no van-accessible space (if parking lot provided) spaces +/-for aisles not level > 2.08% | 1A | Priority 3 | Approach & Entrance | Provide designated accessible parking spaces at a level area closer to the entrance. | \$2,610.00 | 2017 | | City Clerk | | |
| Liberty Christian Center | 6-129 | | Sidewalks + Walkways | no accessible route provided from sidewalks to entrance | 1A | Priority 3 | Approach & Entrance | Maintain perimeter sidewalks to be level and slip-resistant | Dependent on distance | 2017 | | City Clerk | | |
| Westville Congregational Parish HS | 6-135 | | Entrance Door | | 1B | Priority 3 | Approach & Entrance | Adjust door pressure and replace threshold with a lower threshold. | \$350.00 | 2017 | | City Clerk | | |
| Westville Congregational Parish HS | 6-179 | | Parking | If designated accessible ____ access aisle does not connect to accessible route van-accessible space + aisle= inadequate dimensions | 1B | Priority 3 | Approach & Entrance | Relocate accessible parking to the most level area and as close to the accessible entrance as possible. Mount signs at 60" above the ground, and ensure that one space is van accessible. | \$2,610.00 | 2017 | | City Clerk | | |
| Westville Congregational Parish HS | 6-137 | | Sidewalks + Walkways | | 1B | Priority 3 | Approach & Entrance | At ramp, secure mat, bevel end of ramp, and ensure there is an accessible route from accessible parking area. | Dependent on distance | 2017 | | City Clerk | | |
| Westville Congregational Parish HS | 6-138 | | Sidewalks + Walkways | | 1B | Priority 3 | Approach & Entrance | Make sure pavement is uniformly level on entrance route. | Dependent on distance | 2017 | | City Clerk | | |
| Westville Congregational Parish HS | 6-136 | | Sidewalks + Walkways | no accessible route provided from sidewalks to entrance Sidewalks poorly maintained and unusable | 1B | Priority 3 | Approach & Entrance | If construction is ongoing during polling even, ensure that the sidewalk barriers lead pedestrians to an accessible route to the front entrance. | \$0.00 | 2016 | | City Clerk | | |
| Westville Congregational Parish HS | 6-180 | | Sidewalks + Walkways | no accessible route provided from sidewalks to entrance Sidewalks poorly maintained and unusable | 1B | Priority 3 | Approach & Entrance | If construction is ongoing during polling even, ensure that the sidewalk barriers lead pedestrians to an accessible route to the front entrance. | \$0.00 | 2016 | | City Clerk | | |
| Fitzsimmons Arms Community Hall (CoA) | 6-140 a | | Entrance Door | Doorway at-grade but transition > 1/2" | 2A | Priority 3 | Approach & Entrance | replace threshold with a lower threshold. | \$350.00 | 2016 | Nov-16 | City Clerk | completed | see m19-027 |
| Fitzsimmons Arms Community Hall (CoA) | 6-140 b | | Entrance Door | Door too heavy | 2A | Priority 3 | Approach & Entrance | Adjust door pressure . | \$350.00 | 2016 | Nov-16 | City Clerk | completed | |
| Fitzsimmons Arms Community Hall (CoA) | 6-139 | | Sidewalks + Walkways | | 2A | Priority 3 | Approach & Entrance | Repair deteriorated surfaces of walkway. | Dependent on distance | 2017 | | City Clerk | | |
| Fitzsimmons Arms Community Hall (CoA) | 6-141 | | Voting Area | Accessible voting table separated from general area / route AutoMARK Privacy Hood not attached Paper tray not in ready (out) position | 2A | Priority 1 | Program Access | Provide accessible voting features in as integrated a manner as possible, and not overlapping with staff areas. Provide a sturdy lightweight chair and an automark privacy hood. | \$350.00 | 2016 | Nov-16 | City Clerk | completed | |
| Temporary City Hall | 6-142 | | Sidewalks + Walkways | | 2B | Priority 3 | Approach & Entrance | Repair excessive cross slopes | Dependent on distance | 2016 | Aug-17 | City Clerk | completed | cross slope under 2% |
| Temporary City Hall | 6-182 | | Voting Area | Headphones not attached / provided AutoMARK Privacy Hood not attached Accessible voting table separated from general area / route | 2B | Priority 1 | Program Access | Provide accessible voting features in as integrated a manner as possible. Clear route of pole-mounted objects and ensure there is a 36" wide clear route. Provide a sturdy chair and privacy hood and headphones. | \$350.00 | 2016 | Nov-16 | City Clerk | completed | |
| E. Pole Elem. School - 3A and B | pic in narrative has no # | | Election Systems and Software (ES&S) AutoMARK | Accessible table not along accessible route AutoMARK not along accessible route | 3A and 3B | Priority 1 | Program Access | Provide accessible voting features in as integrated a manner as possible. Clear route of pole-mounted objects and ensure there is a 36" wide clear route. Provide a sturdy chair and privacy hood and headphones. | \$350.00 | 2016 | Nov-16 | City Clerk | completed | |
| E. Pole Elem. School - | 6-112 | | Voting Area | Accessible voting table separated from general area / route AutoMARK Privacy Hood not attached Chair provided at AutoMARK table, but not secure (for example, light folding chairs are not secure b/c they move easily on contact) | 3A and 3B | Priority 1 | Program Access | Provide accessible voting features in as integrated a manner as possible. Clear route of pole-mounted objects and ensure there is a 36" wide clear route. Provide a sturdy chair and privacy hood and headphones. | \$350.00 | 2016 | Nov-16 | City Clerk | completed | |
| Joseph Martin School | 6-116 | | Parking | spaces +/-for aisles not level > 2.08% spaces not on shortest route to entrance | 4A | Priority 3 | Approach & Entrance | ensure that accessible parking spaces are close to entrance and don't have excessive slopes | \$1,740.00 | 2017 | Nov-18 | City Clerk | completed | |
| Joseph Martin School | 6-114 | | Sidewalks + Walkways | Sidewalks poorly maintained and unusable | 4A | Priority 3 | Approach & Entrance | Address excessive cross slopes. | Dependent on distance | 2017 | Nov-18 | City Clerk | completed | |
| Joseph Martin School | 6-123 | | Voting Area | Accessible voting table separated from general area / route AutoMARK Privacy Hood not attached Chair provided at AutoMARK table, but not secure (for example, light folding chairs are not secure b/c they move easily on contact) | 4A | Priority 1 | Program Access | Provide accessible voting features in as integrated a manner as possible. Provide a sturdy chair, and privacy hood. | \$350.00 | 2016 | Nov-16 | City Clerk | completed | |

| | | | | | | | | | | | | | | | | |
|--------------------------------------|--------------|--|---|--|---------------|----|------------|------------------------------|---|--------------------------------------|--|------|-----------|------------|-----------|-----------------------|
| East Taunton Elem. School | 6-121, 6-120 | | Parking | spaces +/-for aisles not level >2.08% access aisle does not connect to accessible route route provided from parking to entrance | no accessible | 4B | Priority 3 | Approach & Entrance | Regrade or relocate accessible parking spaces to be on a level area and as close to the entrance as possible. Ensure that access aisle connects to an accessible route. | \$3,480.00 | | 2017 | | City Clerk | | |
| East Taunton Elem. School | 6-122 | | Election Systems and Software (ES&S) AutoMARK | | | 4B | Priority 4 | Access to Goods and Services | Ensure that there is a privacy hood at accessible voting stations. | \$100.00 | | 2016 | Nov-16 | City Clerk | completed | |
| East Taunton Elem. School | 6-124 | | Election Systems and Software (ES&S) AutoMARK | Accessible voting station Knee clearance < 27" | | 4B | Priority 4 | Access to Goods and Services | When setting up portable voting tables, adjust height so that there is at least 27" of clear space under the table. | \$50.00 | | 2016 | Nov-16 | City Clerk | completed | |
| Hopewell Elementary School | 6-148 | | Parking - Curb ramp | curb ramp landings > 2.08% ramp cross slopes > 2.08% ramp slope exceeds 8.3% % | | 5A | Priority 3 | Approach & Entrance | Address the excessive cross slope and the slope at the ramp. | Dependent on distance | | 2017 | | City Clerk | deferred | |
| Hopewell Elementary School | 6-147 | | Sidewalks + Walkways | | | 5A | Priority 3 | Approach & Entrance | Provide edge protection for ramp and repair 1.5" gap at end of ramp. | \$710.00 | | 2017 | | City Clerk | deferred | |
| Hopewell Elementary School | 6-149 | | Sidewalks + Walkways | | | 5A | Priority 3 | Approach & Entrance | Install a visible and audible intercom, replace threshold with lower threshold, secure mats. | \$2,584.00 | | 2017 | | City Clerk | deferred | |
| Hopewell Elementary School | 6-152 | | Sidewalks + Walkways | | | 5A | Priority 4 | Access to Goods and Services | sidewalks | | | 2016 | Nov-16 | City Clerk | completed | |
| Hopewell Elementary School | 6-154 | | Election Systems and Software (ES&S) AutoMARK | | | 5A | Priority 4 | Access to Goods and Services | objects in way | | | 2016 | Nov-16 | City Clerk | completed | |
| Hopewell Elementary School | 6-155 | | Election Systems and Software (ES&S) AutoMARK | | | 5A | Priority 4 | Access to Goods and Services | Move any protruding objects and provide a privacy hood. | \$150.00 | | 2016 | Nov-16 | City Clerk | completed | |
| Hopewell Elementary School | 6-150 | | Sidewalks + Walkways | | | 5A | Priority 4 | Access to Goods and Services | tape mats | \$5.00 | | 2016 | Nov-16 | City Clerk | completed | |
| Joseph Chamberlain Elementary School | 6-181 | | Sidewalks + Walkways | Sidewalks poorly maintained and unusable no accessible route provided from sidewalks to entrance no accessible route provided from parking to entrance | | 5B | Priority 3 | Approach & Entrance | Repair deteriorated walkway so that it is smooth, level and slip resistant with slopes not exceeding 5% and cross slopes not exceeding 2.08%. Repair ramp to include a level top landing, and repair excessive bevel at the bottom of the ramp. | Dependent on distance | | 2016 | | City Clerk | | |
| Craig C. Sherman Cntr (DPW) | 6-156 | | Sidewalks + Walkways | no accessible route provided from sidewalks to entrance Sidewalks poorly maintained and unusable | | 6A | Priority 3 | Approach & Entrance | Include info for voters to let them know that the facility has a large parking lot with 4 accessible parking spaces. Update voters on sidewalk access from the nearby bus routes in the description. | Dependent on distance/cost of media. | | 2016 | fall 2016 | City Clerk | completed | see dpw |
| Leddy School | 6-158, 6-157 | | Sidewalks + Walkways | no accessible route provided from parking to entrance no accessible route provided from sidewalks to entrance poorly maintained and unusable | Sidewalks | 6B | Priority 3 | Approach & Entrance | Ensure that the sidewalk alterations around the perimeter of the School are completed and provide a compliant accessible route to the accessible entrance from nearby streets and sidewalks. | Dependent on distance | | 2016 | fall 2016 | City Clerk | completed | see ledly school |
| Mulcahey School | 6-159 | | Sidewalks + Walkways | | | 7A | Priority 3 | Approach & Entrance | Resurface the exterior entry way so that running slopes don't exceed 5% and cross slopes do not exceed 2.08%. | Dependent on distance | | 2017 | | City Clerk | deferred | |
| Mulcahey School | 6-160 | | Sidewalks + Walkways | | | 7A | Priority 3 | Approach & Entrance | Prop open existing entry door. | \$0.00 | | 2016 | | City Clerk | deferred | |
| Bennett School | 6-126 | | Election Systems and Software (ES&S) AutoMARK | | | 7B | Priority 1 | Program Access | locate voting equipment so that door maneuvering clearance is adequate. | \$50.00 | | 2016 | Nov-16 | City Clerk | completed | |
| Bennett School | 6-127 | | Election Systems and Software (ES&S) AutoMARK | | | 7B | Priority 1 | Program Access | Repair walkway so that cross slopes and running slopes are accessible. | Dependent on distance | | 2016 | Aug-17 | City Clerk | completed | |
| Bennett School | 6-128 | | Election Systems and Software (ES&S) AutoMARK | | | 7B | Priority 1 | Program Access | Provide accessible voting features in as integrated a manner as possible. Provide a sturdy chair, and privacy hood. | \$350.00 | | 2016 | Nov-16 | City Clerk | completed | |
| Benjamin Friedman School | 6-171 | | Parking | # of designated accessible ____ # of spaces ____ (total) access aisle does not connect to accessible route | | 8A | Priority 3 | Approach & Entrance | Repair cross slopes at accessible parking spaces and walkways. Consider providing tactile strips where the traffic intersects with pedestrian paths. | Dependent on distance | | 2016 | | City Clerk | | |
| Benjamin Friedman School | 6-172 | | Sidewalks + Walkways | no accessible route provided from parking to entrance | | 8A | Priority 3 | Approach & Entrance | Consider providing tactile strips where the traffic intersects with pedestrian paths. | Dependent on distance | | 2016 | | City Clerk | | |
| North Taunton Baptist Church | 6-164 | | Entrance Door | | | 8B | Priority 2 | Safety | Secure walkoff mats | \$200.00 | | 2016 | Nov-16 | City Clerk | completed | carpet removed during |
| North Taunton Baptist Church | 6-175 | | Entrance Door | | | 8B | Priority 3 | Approach & Entrance | Pave strip leading to entrance ramp and repair excessive slopes along entry route. | Dependent on distance | | 2017 | | City Clerk | | |
| North Taunton Baptist Church | 6-178 | | Entrance Door | No sign at inaccessible door to accessible entrance | | 8B | Priority 3 | Approach & Entrance | Provide a directional sign | \$260.00 | | 2016 | | City Clerk | | |
| North Taunton Baptist Church | 6-174 | | Sidewalks + Walkways | | | 8B | Priority 3 | Approach & Entrance | Relocate vote sign so that it is out of the 36" accessible route required for entering the building. | \$50.00 | | 2016 | | City Clerk | | |
| North Taunton Baptist Church | 6-163 | | Sidewalks + Walkways | Sidewalks poorly maintained and unusable no accessible route provided from sidewalks to entrance | | 8B | Priority 3 | Approach & Entrance | Maintain perimeter sidewalks to be level and slip-resistant. | Dependent on distance | | 2016 | | City Clerk | | |
| TOTAL** | | | | | | | | | | \$18,249.00 | | | | | | |